



DCD 4600	
RSB-4680	
Release Note	
	D 1 1W : W2600
	Released Version:V2600 Released Date: 2019-11-18

Advantech Co., Ltd.

http://www.advantech.com/

ABSTRACT

This document describes how to use diagnostic tool for board functionality verification.

Copyright Notice

This document is copyrighted, 2012, by Advantech Co., Ltd. All rights are reserved. Advantech

Co., Ltd. reserves the right to make improvements to the products described in this manual at

any time. Specifications are thus subject to change without notice.

No part of this manual may be reproduced, copied, translated, or transmitted in any form or by

any means without the prior written permission of Advantech Co., Ltd. Information provided in

this manual is intended to be accurate and reliable. However, Advantech Co., Ltd., assumes no

responsibility for its use, or for any infringements upon the rights of third parties which may

result from its use.

All the trademarks of products and companies mentioned in this data sheet belong to their

respective owners.

Copyright © 1983-2012 Advantech Co., Ltd. All Rights Reserved

For more information on this and other Advantech products please visit our website at:

http://www.advantech.com

Part No.

Version: 1.00

Printed in Taiwan 2019-12-02

- 2 -

1. Hardware Information

CPU: RK3288 Quad Core DRAM: 2 GB

2. Software Information

This document contains important information about the package contents, supported features, known issues and limitations in this release. This release contains the latest updates for the last general availability (GA) release OS: Android_6.0.1

3. Release Version

Rev	Date	Description	Release by
V1000	2018-07-10	The first release	Wei.zeng
V2100	2018-09-11	MP release	Wei.zeng
V2500	2019-5-17	Alpha release	Wei.zeng
V2600	2019-11-18	MP release	Wei.zeng

4. Add New Features

RSB-4680 is always not into suspend mode.

(1) Follow Advantech wiki:

 $\underline{http://ess-wiki.advantech.com.tw/view/IoTGateway/BSP/Android/Android\ BSP_User\ G}\\ \underline{uide\ 6.0.1\ for\ rk}$

(2) Getting Android Source Code in Wiki.

5. Issues

(1) Fixed Ethernet can't get IP info after dhcp timeout.