

## **Release Notes**

### **EPC-R3220 A1**

Released Version:V1.0  
Released Date: 2021.07.29

Advantech Co., Ltd.

<http://www.advantech.com/>

No.27, Wende Road, Gueishan Township, Taoyuan County 33371, Taiwan,  
R.O.C.

---

---

## ABSTRACT

This document describes how to test for SI/POWER/QA with RISC EPC-R3220 platform.

---

---

## Copyright Notice

This document is copyrighted, 2019, by Advantech Co., Ltd. All rights are reserved. Advantech Co., Ltd. reserves the right to make improvements to the products described in this manual at any time. Specifications are thus subject to change without notice.

No part of this manual may be reproduced, copied, translated, or transmitted in any form or by any means without the prior written permission of Advantech Co., Ltd. Information provided in this manual is intended to be accurate and reliable. However, Advantech Co., Ltd., assumes no responsibility for its use, or for any infringements upon the rights of third parties which may result from its use.

All the trade marks of products and companies mentioned in this data sheet belong to their respective owners.

Copyright © 2019 Advantech Co., Ltd. All Rights Reserved

For more information on this and other Advantech products please visit our website at :

<http://www.advantech.com>

Part No.

Version: 1.0

Printed in Taiwan 2021-08-06

---

# Table of Contents

---

Advantech Co., Ltd. ....	1
Advantech Co., Ltd .....	1
1. Hardware Information.....	4
2. Software Information.....	4
● Release Contents.....	4
<b>This document contains important information about the package contents, supported features, known issues and limitations in this release. This release contains the latest updates for the last general availability release.....</b>	<b>4</b>
● OS: Linux Yocto Project 2.4 (Rocko).....	4
● U-Boot: 2018.01 .....	4
● Linux OS Kernel and Device Trees: 4.14.79+ (2018 LTS) .....	4
3. Release Version .....	4
4. Add New Features .....	4
5. Fixed Bugs .....	4
6. Won't Fixed Bug.....	4
7. Known Issues .....	5
8. Limitations .....	5

## 1. Hardware Information

Board	CPU	DRAM
EPC-R3220	AM3352	1G

## 2. Software Information

### ● Release Contents

This document contains important information about the package contents, supported features, known issues and limitations in this release. This release contains the latest updates for the last general availability release.

- OS: Linux Yocto Project 2.4 (Rocko)
- U-Boot: 2018.01
- Linux OS Kernel and Device Trees: 4.14.79+ (2018 LTS)

## 3. Release Version

Rev	Date	Description	Remark	Released by
V20000	2019/08/30	The first release	QE test	Zhengguang.Yang
V20002	2020/02/19	Fix the problem that the system will restart again after restarting	QE test	Zhengguang.Yang
V20012	2020/07/29	Since MSP430 WDT FW is modified correctly, the fixed frequency during WDT operation is removed	Alpha test	Zhengguang.Yang

## 4. Add New Features

Features	Description	Comment

## 5. Fixed Bugs

Bug ID	Issue	Description

## 6. Won't Fixed Bug

Bug ID	Issue	Description

## 7. Known Issues

Features	Description	Resolution/Workaround

## 8. Limitations

Features	Description	Resolution/Workaround

