


Enabling an Intelligent Planet



Released Version:V1.0 Released Date: 2019.08.15

Advantech Co., Ltd.

EMST (Embedded Media & Smart Technology)-RISC http://www.advantech.com/ No.33, Lane 365, Yang Guang Street, Neihu District, Taipei, Taiwan 11468, R.O.C.

ABSTRACT This document describes how to use diagnostic tool for board functionality verification.

Copyright Notice

This document is copyrighted, 2019, by Advantech Co., Ltd. All rights are reserved. Advantech Co., Ltd. reserves the right to make improvements to the products described in this manual at any time. Specifications are thus subject to change without notice.

No part of this manual may be reproduced, copied, translated, or transmitted in any form or by any means without the prior written permission of Advantech Co., Ltd. Information provided in this manual is intended to be accurate and reliable. However, Advantech Co., Ltd., assumes no responsibility for its use, or for any infringements upon the rights of third parties which may result from its use.

All the trademarks of products and companies mentioned in this data sheet belong to their respective owners.

Copyright © 1983-2019 Advantech Co., Ltd. All Rights Reserved

For more information on this and other Advantech products please visit our website at : <u>http://www.advantech.com</u>

Part No. Version: 1.0

Printed in Taiwan 2019-08-23

Table of Contents

Ad	Advantech Co., Ltd		
1.	Hardware Information	4	
2.	Software Information	4	
3.	Release Version	4	
4.	Add New Features	4	
5.	Fixed Bugs	4	
6.	Won't Fixed Bugs	5	
7.	Known Issues	5	
8.	Limitations	5	

1. Hardware Information

- CPU: i.MX6 Dual Core/Quad Core
- DRAM: 1 GB

2. Software Information

- Release Contents: This document contains important information about the package contents, supported features, known issues and limitations in this release. This release contains the latest updates for the last general availability (GA) release.
- OS: Linux Yocto Project 2.5 (Sumo) 4.14.98-2.0.0_ga
- U-Boot: 2018.03
- Linux OS Kernel and Device Trees: 4.14.98

3. Release Version

Rev	Date	Description	Remark	Released by
V90017	2019/08/05	The first release	Alpha release	Darren Huang
V90019	2019/08/22	Fix SATA Boot, mtd1 access, LVDS issues	Alpha release	Darren Huang

4. Add New Features

Features	Description	Comment

5. Fixed Bugs

Bug ID	Issue	Description
None	SATA Boot can't work fine	

None	mtd1 access fail	spi_imx 2018000.ecspi: I/O Error in DMA TX
		m25p80 spi4.0: SPI transfer failed: -110
		spi_master spi4: failed to transfer one message from
		queue
		hexdump: /dev/mtd1: Connection timed out
None	LVDS can't work fine	

6. Won't Fixed Bugs

Bug ID	Issue	Description
None		

7. Known Issues

Features	Description	Resolution/Workaround
None		

8. Limitations

Features	Description	Resolution/Workaround