

Release Notes	
ROM-3710 A2	
	Released Version:V1005 Released Date: 2021.12.15

Advantech Co., Ltd.

EMST (Embedded Media & Smart Technology)-RISC

http://www.advantech.com/

No.1, Alley 20, Lane 26, Rueiguang Road, Neihu District, Taipei 114519, Taiwan

ABSTRACT

This document describes how to use diagnostic tool for board functionality verification.

Copyright Notice

This document is copyrighted, 2021 by Advantech Co., Ltd. All rights are reserved. Advantech Co., Ltd. reserves the right to make improvements to the products described in this manual at

any time. Specifications are thus subject to change without notice.

No part of this manual may be reproduced, copied, translated, or transmitted in any form or by

any means without the prior written permission of Advantech Co., Ltd. Information provided in

this manual is intended to be accurate and reliable. However, Advantech Co., Ltd., assumes no responsibility for its use, or for any infringements upon the rights of third parties which may

result from its use.

All the trademarks of products and companies mentioned in this data sheet belong to their

respective owners.

Copyright © 1983-2021 Advantech Co., Ltd. All Rights Reserved

For more information on this and other Advantech products please visit our website at:

http://www.advantech.com

Part No.

Version: 1.1

Table of Contents

Ad	.dvantech Co., Ltd错词	· - - - - - - - - - - - - - - - - - - -
1.	Hardware Information	4
2.	Software Information	4
3.	Release Version	4
4.	Add New Features	4
5.	Fixed Bugs	4
	Won't Fixed Bugs	
	Known Issues	
	Limitations	

1. Hardware Information

• CPU: RK3399

2. Software Information

- Release Contents: This document contains important information about the package contents, supported features, known issues and limitations in this release. This release contains the latest updates for the last Alpha release.
- OS: Android10
- U-Boot: 2017.09
- Linux OS Kernel and Device Trees: 4.19.111

3. Release Version

Rev	Date	Description	Remark	Released by
V1005	2021/12/15	The first release	Alpha release	Yunjin.Jiang

4. Add New Features

Features	Description	Comment

5. Fixed Bugs

Bug ID	Issue	Description

6. Won't Fixed Bugs

Bug ID	Issue	Description

7. Known Issues

Features	Description	Resolution/Workaround

8. Limitations

Features	Description	Resolution/Workaround
UIO-4030	Function isn't tested.	
UIO-4036	Function isn't supported.	